



INSTALLATION INSTRUCTIONS



STEP BY STEP FOR VECTOR SEATING SYSTEM TRI-HUB CONFIGURATION







## Place bench, top down

• Securely place bench, top down, on top of a padded surface.

## **Attach legs**

- Position leg with edge of bench seat.
- Insert 3/8"-16 x 3/4" button head cap bolt (b) into mounting holes in bench and thread into holes.
- Repeat with all benches ensuring that end/intermediate legs are used appropriately.


#### Position bench


- Carefully turn bench right side up; you will need another person to hold the bench and/or a sturdy box to provide support until benches are attached; they will not stand alone. Use padding where necessary.
- Position bench in desired location. Be sure that the space allows enough room for full configuration.


FORMS+SURFACES®

INSTALLATION INSTRUCTIONS

# STEP BY STEP FOR VECTOR SEATING SYSTEM TRI-HUB CONFIGURATION







### Attach second 120° bench

- Position the two benches so that connection holes align.
- Once connection holes are aligned insert 3/8"-16 x 3/4" button head cap bolt (b) into bench connection holes.

Note: Although two benches are connected they will not stanalone until the third bench is completely attached. You will still need a person and/ or sturdy box to support the configuration after this step.

### Attach third 120° bench

- Position the third bench so that the conneciton holes align.
- Once connection holes are aligned insert 3/8"-16 x 3/4" button head cap bolt (b) into bench connection holes.


Note: If the Tri-hub is surface mounted continue on to step 6, otherwise installtion is complete.


### Mark surface mount location


- Once module is in the desired location, mark the ground along the inside of each leg including the center notch, indicated by the dashed line.
- Carefully move bench to the side once mounting surfaced is marked.

INSTALLATION INSTRUCTIONS

# STEP BY STEP FOR VECTOR SEATING SYSTEM TRI-HUB CONFIGURATION







#### Position surface mount plate

- Measure and mark 1 1/8" from surface mount mark to find the surface mount plate center line, indicated by the dashed line.
- Position the surface mount plate by first aligning the center notch with the center notch line.
- Next, align the mounting holes and positioning notches to the surface mount plate center line.
- Mark the center of each mounting hole.

#### **Drill holes**

 Use hammer drill to drill 4.5" deep x 3/4" diameter anchor hole at each marked location using a 3/4" drill bit suitable for concrete drilling.

Note: Forms+Surfaces recommends starting holes with 1/4" diameter drill bit followed by 1/2" and finally 3/4" for maximum accuracy.

#### Fill holes & insert anchors


- Use compressed air and steel wire brush to clean each anchor hole in accordance with epoxy instructions.
- Use epoxy gun to fill each anchor hole 5/8 of the hole depth in accordance with epoxy instructions
- Insert 3/8"-16 x 4-1/4" epoxy anchor


   (a) into each anchor hole so anchor top is flush with ground. Allow proper curing time according to cure schedule on epoxy instructions before moving on to Step 10.




INSTALLATION INSTRUCTIONS

STEP BY STEP FOR VECTOR SEATING SYSTEM TRI-HUB CONFIGURATION







### Attach surface mount plate

- Position surface mount plate so that mounting holes line up with anchors.
- Insert 3/8"-16 x 1-1/2" button cap bolts (c) into mounting holes in surface mount plate.

### Fit module onto surface mount plate

• Lift module up and slide leg(s) onto mounted surface mount plate(s).

## Attach leg to surface mount plate

- Ensure that leg mounting hole and surface mount plate mounting hole align.
- Insert 3/8"-16 x 3/4" tamper-resitant button head cap bolt (d) into bench connection holes using 7/32" hex bit for tamper-resistant bolts.